


STRIKEMASTER 40V LITHIUM ICE AUGER

POWERHEAD EXPLODED VIEW



StrikeMaster 40V Warranty Price & Labor Guide

ITEM NO.	PART NO.	DESCRIPTION	Warranty Time Allotment INCLUDES ALL STEPS
1	339011755	Hex Wrench	(
2	211012180	40V 5Ah Battery	Replace Battery Pack
3	311041755	PCB Assy.	30 Minutes
4	311011755	Main Handle Assy.	120 Minutes * replace powerhead*
5	332021755	Ring Gear	Replace 13
6	311031755	Flange Assy.	5 Minutes
7	322011755	Gear Screw	Replace 13
8	361011755	Motor	35 Minutes
9	363021755	Rocker Switch	15 Minutes
10	332031755	Planel Carrier	Replace 13
11	363011755	Variable speed switch	Replace 4
12	332041755	Output shaft	Replace 13
13	311021755	Gear Box Assy.	60 Minutes
16	332091755	1st Planet Gear	Replace 13
17	341021755	Top Housing and Decal	5 Minutes
18	341071755	Top Housing Support	10 Minutes
19	341031755	Bottom Housing	60 Minutes
20	341011755	Main Handle	140 Minutes *replace powerhead*
21	332081755	2nd Planet Gear	Replace 13
24	33401871	Spring	5 Minutes
25	341121755	Light Cup	5 Minutes
26	341131755	Lens	10 Minutes
27	341051755	Right Light Cover	Replace 4
28	331041755	Flange	10 Minutes
34	341061755	Actuator	20 Minutes
35	341041755	Left Light Cup	5 Minutes
36	341111755	Safety Button	5 Minutes
37	341101755	Push Lever	15 minutes
38	341091755	Handle Cover	5 Minutes
39	322021755	Housing Screw	5 Minutes
40	322031755	Housing Screw2	5 Minutes
41	322041755	Housing Screw3	5 Minutes
42	322051755	Housing Screw4	5 Minutes
43	362011755	LED PCB	10 Minutes
44	311011755	Gear Box	Replace 13
45	362021755	PCB Assy	30 Minutes
46	341012181	Battery Pin	40 Minutes
47	349011755	Wool Cushion2	Replace 13
48	349021755	Wool Cushion	15 Minutes
49	321011755	Ball Bearing	20 Minutes
50	329011755	Ring SWT-25	15 Minutes
51	333031755	Shaft Plate	20 Minutes
52	322061755	Drill Screw to Auger	(SM COLLARBOLT)
53	333021755	Motor Plate	Replace 13
54	342011755	Motor Rubber	15 Minutes
55	341081755	Actuator Button	10 Minutes
56	333011755	Gear Plate	Replace 13
57	211012181	40V Charger	Replace Charger